

DEC 10 2013

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

30-025-12285

Operator Name CHAPARRAL ENERGY LLC		API Number 30025122850000
Property Name WEST DOWARTIDE QUEEN SAND UNIT		Well No. 33

7. Surface Location

UL - Lot 37	Section 31	Township 24S	Range 38E	Feet from 1750	N/S Line FNL	Feet From 2210	E/W Line FNL	County Lea
-----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
-------------	---------	-----------	------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0				350
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	☒ Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

WATER COMING OUT OF CASING. FAILED TEST, 9-17-13

Signature: William Dunlap		OIL CONSERVATION DIVISION
Printed name: WILLIAM DUNLAP		Entered into RBDMS
Title: Prod. Tech		Re-test
E-mail Address:		
Date: 9-17-13	Phone: 405-227-4298	
Witness:		

DEC 10 2013