

DEC 10 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHAPARRAL ENERGY LLC		API Number 30025301960000
Property Name West Dolar Hido Queen Sand Unit		Well No. 108

7. Surface Location

UL - Lot 37	Section 29	Township 24S	Range 38E	Feet from 2310	N/S Line E/NL	Feet From 380	E/W Line FWL	County Lea
-----------------------	----------------------	------------------------	---------------------	--------------------------	-------------------------	-------------------------	------------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
-------------	---------	-----------	------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0				250
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

water coming out of casing. Failed test 9/17/13

FAILED
MW 12/10/13

Signature: William Dundy		OIL CONSERVATION DIVISION
Printed name: William Dundy		Entered into RBDMS
Title: Prod. Tech		Re-test
E-mail Address:		
Date: 9-17-13	Phone: 405-227-4298	
Witness:		

DEC 1 2013