

HOBBS OCD

DEC 10 2013

State of New Mexico  
 Energy, Minerals and Natural Resources Department  
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

30-025-30231

Operator Name <b>CHAPARRAL ENERGY LLC</b>		API Number <b>30025302310000</b>	
Property Name <b>West DALLARHIDE Queen SAND UNIT</b>		Well No. <b>113</b>	

1. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
37	31	24S	38E	330	FWL	2360	FWL	LEA

Well Status

Well Status	SHUT-IN	PRODUCING	DATE

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod Casing	(E) Tubing
Pressure	0				450
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

water coming out of casing Failed test 9/17/13

Signature: <i>William Dunlap</i>	OIL CONSERVATION DIVISION
Printed name: William Dunlap	Entered into RBDMS
Title: Prod. Tech	Re-test
E-mail Address:	
Date: 9-17-13	Phone: 505-227-4298
Witness:	

DEC 10 2013