

DEC 10 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHAPARRAL ENERGY LLC		API Number 30025302950000
Property Name WEST DOLLAR HIDE QUEEN SAND UNIT		Well No. 135

7. Surface Location

UL - Lot 37	Section 32	Township 24S	Range 38E	Feet from 2100	N/S Line FWL	Feet From 1630	E/W Line FWL	County LEA
-----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
-------------	---------	-----------	------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Casing	(E)Tubing
Pressure	0				300
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Water Coming out of Casing. Failed test 9/17/13

FAILED
MW 12/10/13

Signature: William Dunlap		OIL CONSERVATION DIVISION
Printed name: WILLIAM DUNLAP		Entered into RBDMS
Title: Prod. Tech		Re-test
E-mail Address:		
Date: 9-17-13	Phone: 405-227-4298	
Witness:		

DEC 10 2013