

DEC 05 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <i>Cherron Mud Treatment L.P.</i>	API Number <i>30-025-03825</i>
Property Name <i>Lovington Paddock Unit</i>	Well No. <i>48</i>

7. Surface Location									
UL - Lot <i>B</i>	Section <i>1</i>	Township <i>17d</i>	Range <i>36E</i>	Feet from <i>660</i>	N/S Line <i>FWL</i>	Feet from <i>2080</i>	E/W Line <i>FEL</i>	County <i>LEA</i>	

Well Status

Well Status <i>A</i>	SHUT-IN <i>Active</i>	PRODUCING <i>Trig ✓</i>	DATE <i>10/14/2013</i>
-------------------------	--------------------------	----------------------------	---------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	<i>0</i>		<i>0</i>		<i>1860</i>
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

CLAS/OCD 12/11/2013
COMPLIANCE OFFICER

Signature: <i>Danny Acosta</i>	OIL CONSERVATION DIVISION
Printed name: <i>Danny Acosta</i>	Entered into RBDMS
Title: <i>ALCR</i>	Re-test
E-mail Address: <i>DNLC@chevron.com</i>	
Date: <i>10/14/2013</i>	Phone: <i>575-631-9033</i>
Witness:	

DEC 11 2013