

DEC 05 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <i>Cherron Child Courtney, S.P.</i>	API Number <i>30-025-05356</i>
Property Name <i>Lovington Paddock Unit</i>	Well No. <i>37</i>

7. Surface Location									
UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County	
<i>N</i>	<i>31</i>	<i>16S</i>	<i>37E</i>	<i>330</i>	<i>S</i>	<i>2290</i>	<i>W</i>	<i>LEA</i>	

Well Status			
Well Status <i>A</i>	SHUT-IN <i>Active</i>	PRODUCING <i>Intj</i> ✓	DATE <i>10/17/2013</i>

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	<i>0</i>	<i>600</i>	<i>0</i>		<i>1800</i>
Flow Characteristics					
Puff	Y / N	Y / <i>N</i>	Y / N	Y / N	
Steady Flow	Y / N	<i>Y</i> / N	Y / N	Y / N	
Surges	Y / N	Y / <i>N</i>	Y / N	Y / N	
Down to nothing	Y / N	<i>Y</i> / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / <i>N</i>	Y / N	Y / N	
Water	Y / N	<i>Y</i> / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR ✓	FRESH	SALTY	SULFUR	BLACK
---------	-------	-------	--------	-------

Remarks:

600# blew down to 0#. (Clear water) ✓

JAS/OCD 12/11/2013
COMPLIANCE OFFICER

Signature: <i>Danny Acosta</i>	OIL CONSERVATION DIVISION
Printed name: <i>Danny Acosta</i>	Entered into RBDMS
Title: <i>ALCR</i>	Re-test
E-mail Address: <i>DNHC@chevron.com</i>	
Date: <i>10-17-2013</i>	Phone: <i>575-631-9033</i>
Witness:	

DEC 11 2013