

DEC 05 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <i>✓</i> <u>Chevron</u>	API Number <u>30-025-03787</u>
Property Name <i>✓</i> <u>Lovington San Andreas Unit</u>	Well No. <u>26</u>

7. Surface Location

UL - Lot <u>N</u>	Section <u>36</u>	Township <u>16</u>	Range <u>36E</u>	Feet from <u>660</u>	N/S Line <u>FSL</u>	Feet from <u>1980</u>	E/W Line <u>FWL</u>	County <u>LEA</u>
----------------------	----------------------	-----------------------	---------------------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status <i>✓</i> <u>A</u>	SHUT-IN <u>Actual</u>	PRODUCING <u>Try</u>	DATE <u>10/15/2013</u>
----------------------------------	--------------------------	-------------------------	---------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm (1) - Interm (2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	<u>Ø</u>		<u>Ø</u>		<u>1850</u>
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

✓ ASD/OCD 12/11/2013

COMPLIANCE OFFICER

Signature: <i>✓</i> <u>Danny Acosta</u>	OIL CONSERVATION DIVISION
Printed name: <u>Danny Acosta</u>	Entered into RBDMS
Title: <u>ALCR</u>	Re-test
E-mail Address: <u>DNLAC@chevron.com</u>	
Date: <u>10/15/2013</u>	
Phone: <u>575-631-9033</u>	
Witness:	

DEC 12 2013