

DEC 05 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <i>Chevron Midcontinent SP</i>	API Number <i>30-025-03813</i>
Property Name <i>Lovington San Andreas Unit</i>	Well No. <i>40</i>

Surface Location

U/L Lot <i>H</i>	Section <i>1</i>	Township <i>17S</i>	Range <i>36E</i>	Feet from <i>1980</i>	N/S Line <i>FNL</i>	Feet From <i>660</i>	E/W Line <i>FEL</i>	County <i>LEA</i>
---------------------	---------------------	------------------------	---------------------	--------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

Well Status <i>A</i>	SHUT-IN <i>Active</i>	PRODUCING <i>Intg</i>	DATE <i>10/15/13</i>
-------------------------	--------------------------	--------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm (1-Interm (2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	<i>Ø</i>	<i>Ø</i>	<i>Ø</i>		<i>1900</i>
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

UAD/OCD 12/11/2013

Signature: <i>Danny Acosta</i>	COMPLIANCE OFFICER
Printed name: <i>Danny Acosta</i>	OIL CONSERVATION DIVISION
Title: <i>ALCR</i>	Entered into RBDMS
E-mail Address: <i>DNLAC@chevron.com</i>	Re-test
Date: <i>10/15/13</i>	
Phone: <i>575-631-9033</i>	
Witness:	

DEC 12 2013