

DEC 05 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

Operator Name

✓ Chevron And Continental L.P.

API Number

30-025-03874

Property Name

✓ West Livingston Unit

Well No.

13

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
F	4	178	36E	1980	FNL	1980	FNL	LEA

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
✓ A	Actual	Inj ✓	10/18/13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:


	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	0	0	0		1600
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

WAD/OCD 12/11/2013
COMPLIANCE OFFICER

Signature: 	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: ALCR	Re-test
E-mail Address: DNLC@chevron.com	
Date: 10/18/13	Phone: 575-631-9033
Witness:	

DEC 12 2013