

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name <u>Chervon Midcontinent SP.</u>	API Number <u>30-025-05406</u>
Property Name <u>Lovington San Andreas Unit</u>	Well No. <u>36</u>

7. Surface Location

U/L - Lot <u>B</u>	Section <u>06</u>	Township <u>17N</u>	Range <u>37E</u>	Feet from <u>660</u>	N/S Line <u>FNL</u>	Feet from <u>2040</u>	E/W Line <u>FEL</u>	County <u>LEA</u>
-----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status <u>A</u>	SHUT IN ☒	PRODUCING <u>Inj</u>	DATE <u>10/15/13</u>
-------------------------	--	-------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	<u>0</u>	<u>Broke off</u>		<u>0</u>	<u>1000</u>
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Riser broke off - Shut In For Repairs
Not Able to do MIT.

CLANOCO 12/11/2013
COMPLIANCE OFFICER

Signature: <u>[Signature]</u>	OIL CONSERVATION DIVISION
Printed name: <u>Danny Acosta</u>	Entered into RBDMS
Title: <u>ALCR</u>	Re-test
E-mail Address: <u>DNLC@chevron.com</u>	
Date: <u>10/15/13</u>	Phone: <u>575-631-9033</u>
Witness:	

DEC 12 2013