

DEC 05 2013

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

|                                                      |                            |
|------------------------------------------------------|----------------------------|
| Operator Name<br><i>✓</i> Chevron Midcontinent L.P.  | API Number<br>30-025-05423 |
| Property Name<br><i>✓</i> Lovington San Andreas Unit | Well No.<br>38             |

7. Surface Location

|                        |              |                 |              |                   |                 |                   |                 |               |
|------------------------|--------------|-----------------|--------------|-------------------|-----------------|-------------------|-----------------|---------------|
| UL - Lot<br><i>✓</i> F | Section<br>6 | Township<br>17N | Range<br>37E | Feet from<br>1650 | N/S Line<br>FNL | Feet From<br>1980 | E/W Line<br>FWL | County<br>LEA |
|------------------------|--------------|-----------------|--------------|-------------------|-----------------|-------------------|-----------------|---------------|

Well Status

|                           |                          |                         |                    |
|---------------------------|--------------------------|-------------------------|--------------------|
| Well Status<br><i>✓</i> A | SHUT-IN<br><i>Active</i> | PRODUCING<br><i>Try</i> | DATE<br>10/15/2013 |
|---------------------------|--------------------------|-------------------------|--------------------|

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

|                      | (A) Surf-Interm | (B) Interm (1) - Inter (2) | (C) Interm-Prod | (D) Prod-Tubing | (E) Tubing  |
|----------------------|-----------------|----------------------------|-----------------|-----------------|-------------|
| Pressure             | <i>Ø</i>        | <i>400</i>                 | <i>400</i>      |                 | <i>1700</i> |
| Flow Characteristics |                 |                            |                 |                 |             |
| Puff                 | Y / N           | Y / N                      | Y / N           | Y / N           |             |
| Steady Flow          | Y / N           | Y / N                      | Y / N           | Y / N           |             |
| Surges               | Y / N           | Y / N                      | Y / N           | Y / N           |             |
| Down to nothing      | Y / N           | Y / N                      | Y / N           | Y / N           |             |
| Gas or Oil           | Y / N           | Y / N                      | Y / N           | Y / N           |             |
| Water                | Y / N           | Y / N                      | Y / N           | Y / N           |             |

If bradenhead flowed water, check all of the descriptions that apply:

|       |       |       |        |       |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks:

*✓* AD/OGD 12/11/2013

COMPLIANCE OFFICER

|                                     |                           |
|-------------------------------------|---------------------------|
| Signature:<br><i>Danny Acosta</i>   | OIL CONSERVATION DIVISION |
| Printed name:<br>Danny Acosta       | Entered into RBDMS        |
| Title:<br>A.L.C.R.                  | Re-test                   |
| E-mail Address:<br>DNLC@chevron.com |                           |
| Date:<br>10/15/2013                 | Phone:<br>575-631-9033    |
| Witness:                            |                           |

DEC 12 2013