

HOBBS OCD

DEC 05 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name

API Number

✓ Chevron Midcontinent LP

30-025-05466

Property Name

Well No.

✓ Lovington San Andreas Unit

34

7. Surface Location

Utr. Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
✓ D	6	17d	37E	660	ENL	660	FWL	LEA

Well Status

Well Status	SHUT IN	PRODUCING	DATE
✓ A	✓	Ing	10/15/13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	Ø			Ø	Ø
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK


Remarks:

Plugs in hole.

2 Last Injection Submitted
JAS 5/1/2013
JAS 12/12/2013.

JAS/OCD 12/12/2013.

COMPLIANCE OFFICER

Signature: 	OIL CONSERVATION DIVISION
Printed name: Dany Acosta	Entered into RBDMS
Title: ALCR	Re-test
E-mail Address: DNLC@chevron.com	
Date: 10/15/13	
Phone: 575-631-9033	
Witness:	

DEC 16 2013