

DEC 05 2013,

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron Midcontinent LP	API Number 30-025-03836
Property Name Lovington San Andres Unit	Well No. 30

Surface Location

UL-- Lot 5	Section 1	Township 17N	Range 36E	Feet from 660	N/S Line FNL	Feet From 660	E/W Line FNL	County LEA
----------------------	---------------------	------------------------	---------------------	-------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN ✓	PRODUCING Int	DATE 10/18/13
-------------------------	---------------------	-------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Intern	(B) Intern(1)-Intern(2)	(C) Intern-Prod	(D) Prod-Tubing	(E) Tubing
Pressure					
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

MIT FAILED

**> No Violation ATV his
Time: 8AD/12/11/2013**

8AD/OCD 12/11/2013
COMPLIANCE OFFICER

Signature: Danny Acosta	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: ALC-R	Re-test
E-mail Address: DNLAC@chevron.com	
Date: 10/18/2013	Phone: 575-631-9033
Witness:	

DEC 16 2013