

DEC 13 2013

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 3002530755
Property Name VGSAU	Well No. 179

2. Surface Location

UL - Lot 1A	Section 2	Township 18S	Range 34E	Feet from 1980	N/S Line N	Feet from 12ft	E/W Line E	County Lea
-----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status A	SHUT-IN Oil	PRODUCING X	DATE 11/14/13
-------------------------	-----------------------	-----------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	0		40	210	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	



If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Accepted for Record Only

mmb

Signature: 	OIL CONSERVATION DIVISION
Printed name: Lynda McEwen	Entered into RBDMS
Title: SSPS	Re-test
E-mail Address: lmb@chevron.com	
Date: 12/2/13	Phone: 575-942-3526
Witness:	

DEC 19 2013