

HOBBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 13 2013

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON	* API Number 3002530801
Property Name V6SAU	Well No. 154

7. Surface Location

UL - Lot B	Section 2	Township 18S	Range 74E	Feet from 660	N/S Line N	Feet From 1331	E/W Line E	County Lee
---------------	--------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

A Well Status	SHUT-IN	PRODUCING Oil X	DATE 11/12/13
---------------	---------	--------------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	10	—	30	220	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

A) bled gas down to zero

Accepted for Record Only

MJB

Signature: 	OIL CONSERVATION DIVISION
Printed name: Lynda McQueen	Entered into RBDMS
Title: SSPS	Re-test
E-mail Address: lnnb@chevron.com	
Date: 12/2/13	
Phone: 575-942-3526	
Witness:	

DEC 19 2013