

HOBBS OCD

DEC 13 2013

District I

1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	* API Number 3002502266
Property Name V6SHU	Well No. 51

7. Surface Location

UL - Lot D	Section 2	Township 18S	Range 34E	Feet from 660	N/S Line N	Feet from 660	E/W Line W	County Lea
---------------	--------------	-----------------	--------------	------------------	---------------	------------------	---------------	---------------

Well Status

Well Status A	SHUT-IN	PRODUCING X Oil	DATE 11/14/13
------------------	---------	--------------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	0		35	200	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Accepted for Record Only

MSS

Signature: 	OIL CONSERVATION DIVISION
Printed name: Lynda McWen	Entered into RBDMS
Title: SSPS	Re-test
E-mail Address: lmb@chevron.com	
Date: 12/2/13	Phone: 575-942-3526
Witness:	

DEC 19 2013