

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 13 2013

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	* API Number 3002502247
Property Name CUU	Well No. 90

7. Surface Location

UL - Lot 0	Section 36	Township 17N	Range 34E	Feet from 660	N/S Line F52	Feet from 1980	E/W Line FEL	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN	PRODUCING X Oil	DATE 11/25/13
-------------------------	---------	---------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	0	—	170	525	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Accepted for Record Only
MAB

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: Cyndra McQueen	Entered into RBDMS
Title: SSPS	Re-test
E-mail Address: lrrnb@chevron.com	
Date: 12/2/13	Phone: 575-942-3526
Witness:	

DEC 06 2014