

DEC 13 2013

District I
1625 S. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	API Number 3002502238
Property Name CVU	Well No. 77

7. Surface Location

UL - Lot I	Section 36	Township 17S	Range 34E	Feet from 1980	N/S Line S	Feet From 660	E/W Line E	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

A Well Status	SHUT-IN	PRODUCING X OIL	DATE 11/25/13
---------------	---------	---------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	10	0	155	175	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

A) bleed down to zero pressure ✓

Accepted for Record Only

MSB

Signature: 	OIL CONSERVATION DIVISION
Printed name: Lynda McQueen	Entered into RBDMS
Title: SSPS	Re-test
E-mail Address: lmcq@cherron.com	
Date: 12/2/2013	Phone: 575-942-3526
Witness:	

JAN 06 2014