

DEC 13 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHEVRON	* API Number 3002502240
Property Name CUU	Well No. 78

7. Surface Location

UL - Lot 5	Section 36	Township 17N	Range 34E	Feet from 19W	N/S Line FSL	Feet from 1980	E/W Line FEL	County LEA
---------------	---------------	-----------------	--------------	------------------	-----------------	-------------------	-----------------	---------------

Well Status

Well Status A	SHUT-IN	PRODUCING X OIL	DATE 11/25/13
------------------	---------	--------------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	0	—	190	150	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Accepted for Record Only

MJB

Signature: 	OIL CONSERVATION DIVISION
Printed name: Lynda McQueen	Entered into RBDMS
Title: SSPS	Re-test
E-mail Address: hnb@chevron.com	
Date: 12/2/2013	Phone: 575-942 3526
Witness:	

JAN 06 2014