

District I  
1625 N. French Dr., Hobbs, NM 88240  
Phone: (575) 393-6161 Fax: (575) 393-0720

HOBBS OCD

DEC 18 2013

RECEIVED

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

|                                 |                                 |
|---------------------------------|---------------------------------|
| Operator Name<br><b>CHEVRON</b> | API Number<br><b>3002503076</b> |
| Property Name<br><b>CUU</b>     | Well No.<br><b>97</b>           |

7. Surface Location

|                      |                     |                        |                     |                         |                        |                          |                        |                      |
|----------------------|---------------------|------------------------|---------------------|-------------------------|------------------------|--------------------------|------------------------|----------------------|
| UL - Lot<br><b>C</b> | Section<br><b>6</b> | Township<br><b>18S</b> | Range<br><b>35E</b> | Feet from<br><b>660</b> | N/S Line<br><b>FNL</b> | Feet from<br><b>1810</b> | E/W Line<br><b>FNL</b> | County<br><b>LEA</b> |
|----------------------|---------------------|------------------------|---------------------|-------------------------|------------------------|--------------------------|------------------------|----------------------|

Well Status

|                         |         |                           |                         |
|-------------------------|---------|---------------------------|-------------------------|
| Well Status<br><b>A</b> | SHUT-IN | PRODUCING<br><b>✓ 0.1</b> | DATE<br><b>11/18/13</b> |
|-------------------------|---------|---------------------------|-------------------------|

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

|                      | (A) Surf-Interm | (B) Interm(1)-Interm(2) | (C) Interm-Prod | (D) Prod-Tubing | (E) Tubing |
|----------------------|-----------------|-------------------------|-----------------|-----------------|------------|
| Pressure             | <b>0</b>        |                         | <b>0</b>        | <b>975</b>      |            |
| Flow Characteristics |                 |                         |                 |                 |            |
| Puff                 | Y / N           | Y / N                   | Y / N           | Y / N           |            |
| Steady Flow          | Y / N           | Y / N                   | Y / N           | Y / N           |            |
| Surges               | Y / N           | Y / N                   | Y / N           | Y / N           |            |
| Down to nothing      | Y / N           | Y / N                   | Y / N           | Y / N           |            |
| Gas or Oil           | Y / N           | Y / N                   | Y / N           | Y / N           |            |
| Water                | Y / N           | Y / N                   | Y / N           | Y / N           |            |

If bradenhead flowed water, check all of the descriptions that apply:

|       |       |       |        |       |
|-------|-------|-------|--------|-------|
| CLEAR | FRESH | SALTY | SULFUR | BLACK |
|-------|-------|-------|--------|-------|

Remarks:

Accepted for Record Only

*MSS*

|                                        |                            |
|----------------------------------------|----------------------------|
| Signature: <i>[Signature]</i>          | OIL CONSERVATION DIVISION  |
| Printed name: <b>Lynda McWen</b>       | Entered into RBDMS         |
| Title: <b>SSPS</b>                     | Re-test                    |
| E-mail Address: <b>lmb@chevron.com</b> |                            |
| Date: <b>12/2/13</b>                   | Phone: <b>575 942-3526</b> |
| Witness:                               |                            |

JAN 06 2014