

DEC 13 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-25709
Property Name Central Vacuum Unit	Well No. 85

7. Surface Location

UL - Lot L	Section 31	Township 17S	Range 35E	Feet from 1336	N/S Line F S L	Feet from 1201	E/W Line F W L	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	--------------------------	--------------------------	--------------------------	----------------------

Well Status

Well Status A	SHUT-IN	PRODUCING ✓ Inj	DATE 10/23/12
-------------------------	---------	---------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	0	0	530 → 0	1500	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	0 N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

c - 530# bleed down to 0# - (gas)

Accepted for Record Only

MSB

Signature: 	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: ALCR	Re-test
E-mail Address: DNLAC@chevron.com	
Date: 10/23/12	Phone: 575-631-9033
Witness:	

JAN 06 2014