

DEC 13 2013

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron	API Number 30-025-26078
Property Name Central Vacuum Unit	Well No. 139

7. Surface Location

UL - Lot P	Section 36	Township 17N	Range 34E	Feet from 85	N/S Line FS L	Feet from 958	E/W Line FE L	County LEA
----------------------	----------------------	------------------------	---------------------	------------------------	-------------------------	-------------------------	-------------------------	----------------------

Well Status

Well Status A	SHUT-IN	PRODUCING ✓ Inj	DATE 10/23/13
-------------------------	---------	---------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	Ø	Ø	Ø	1600	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Accepted for Record Only

msb

Signature: <i>Danny Acosta</i>	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: ALCR	Re-test
E-mail Address: DNHC@chevron.com	
Date: 10/23/13	Phone: 575-631-9033
Witness:	

JAN 06 2014