

DEC 13 2013

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6164 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA INC.	API Number 3002503106
Property Name STATE AUV	Well No. 6

2. Surface Location

UL - Lot R	Section 30A	Township E2S	Range 37E	Feet from 1/2 1/4 0 0 0	N/S Line S	Feet from 1/2 1/4 0 0 0	E/W Line E	County Lea
0	7	18S	Well Status 2310					

Well Status A	SHUT-IN X	PRODUCING Oil	DATE 11/2/13
-------------------------	---------------------	-------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	10	0	0	0	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

(A) packer fluid bled down to zero (chemical)
?

Accepted for Record Only

MSE

Signature: 	OIL CONSERVATION DIVISION
Printed name: Lynda McQueen	Entered into RBDMS
Title: SSPS	Re-test
E-mail Address: lmb@chevron.com	
Date: 12/3/13	Phone: 575 942-3526
Witness:	

JAN 07 2014