

DEC 13 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Cherron USA, Inc	API Number 30-025-30799
Property Name Vacuum Grayburg San Andres Unit	Well No. 148

7. Surface Location									
UL Lot D	Section 1	Township 18N	Range 34E	Feet from 1330	N/S Line FWL	Feet from 660	E/W Line FWL	County LEA	

Well Status

Well Status A	SHUT-IN	PRODUCING ✓	DATE 11-4-13
-------------------------	---------	-----------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:


	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	$\emptyset$	$\emptyset$	$\emptyset$		1677
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Accepted for Record Only
MJB

Signature: 	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBEMS
Title: ALCR	Re-test
E-mail Address: DNLC@chevron.com	
Date: 11-4-13	Phone: 575-631-9033
Witness:	

JAN 13 2014