

DEC 13 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chervon WA INC						API Number 30-025-30846			
Property Name Vacuum Grayburg San Andres Unit						Well No. 146			
7. Surface Location									
UL - Lot B	Section 2	Township 18S	Range 34E		Feet from 1325	N/S Line FNL	Feet From 1980	E/W Line FEL	County LEA
Well Status									
Well Status A		SHUT-IN		PRODUCING IN		DATE 11-4-13			

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	Ø	Ø	Ø		736
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Accepted for Record Only

msb

Signature: <i>Danny Acosta</i>		OIL CONSERVATION DIVISION	
Printed name: Danny Acosta		Entered into RBEMS	
Title: ALCR		Re-test	
E-mail Address: DNHC@chevron.com			
Date: 11-4-13	Phone: 575-631-9033		
Witness:			

JAN 13 2014