

DEC 13 2013

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name

Chevron USA Inc.

API Number

30-025-30847

Property Name

VGSAW

Well No.

149

1. Surface Location

UT - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
C	01	18S	34E	1330	FNL	1980	FNL	Lca

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
A		FAJ	11-4-13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod (Tubing)	(E) Tubing
Pressure	0	0	500	1900	
Flow Characteristics					
Puff	Y / N	Y / N	Y / ☒ N	Y / N	
Steady Flow	Y / N	Y / N	☒ / N	Y / N	
Surges	Y / N	Y / N	Y / ☒ N	Y / N	
Down to nothing	Y / N	Y / N	☒ / N	Y / N	
Gas or Oil	Y / N	Y / N	☒ / N	Y / N	
Water	Y / N	Y / N	Y / ☒ N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

C. bleed down in 2 1/2 min All Gas

Accepted for Record Only

MKB

Signature: 	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: ALCR	Re-test
E-mail Address: Dacosta@Chevron.com	
Date: 11-4-13	Phone: 575-6319032
Witness:	

JAN 13 2014

