

DEC 13 2013

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name ✓ Chevron USA, Inc.	API Number 30-025-31700
Property Name ✓ Vacuum Gloria West Unit	Well No. 39

Surface Location

UL - Lot ✓ M	Section 25	Township 178	Range 34E	Feet from 1194	N/S Line FSL	Feet From 1055	E/W Line FWL	County LEA
------------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN	PRODUCING ✓ In	DATE 11-5-13
-------------------------	---------	--------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure					1380
Flow Characteristics	✓		✓		
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Accepted for Record Only
MSB 1/9/2014

Signature: Danny Acosta	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: A.L.C.R.	Re-test
E-mail Address: DNL.C@chevron.com	
Date: 11-5-13	Phone: 575-631-9033
Witness:	

JAN 13 2014