

DEC 13 2013

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name ✓ <i>Chevron USA, Inc.</i>	API Number 30-025-32806
Property Name ✓ <i>Central Vacuum Unit</i>	Well No. 201

7. Surface Location

UL - Lot ✓ <i>5</i>	Section <i>6</i>	Township <i>18N</i>	Range <i>35E</i>	Feet from <i>1360</i>	N/S Line <i>FNL</i>	Feet from <i>1973</i>	E/W Line <i>FEL</i>	County <i>LEA</i>
-------------------------------	---------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status ✓ <i>A</i>	SHUT-IN <i>✓</i>	PRODUCING <i>✓</i>	DATE <i>10-28-13</i>
----------------------------------	---------------------	-----------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	<i>✓</i>	<i>✓</i>	<i>✓</i>	<i>✓</i>	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Shut in due to line.

Accepted for Record Only
MSB

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: <i>Danny Acosta</i>	Entered into RBLMS
Title: <i>ALCR</i>	Re-test
E-mail Address: <i>DNHC@chevron.com</i>	
Date: <i>10-28-13</i>	Phone: <i>575-631-9033</i>
Witness:	

JAN 13 2014