

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 13 2013

BRADENHEAD TEST REPORT

RECEIVED

Operator Name ✓ <i>✓</i> Chevron USA Inc.	API Number 30-025-32809
Property Name ✓ <i>✓</i> Central Vacuum Unit	Well No. 207

7. Surface Location

UL - Lot F	Section 6	Township 18N	Range 35E	Feet from 2500	N/S Line FWL	Feet From 1825	E/W Line FWL	County LEA
----------------------	---------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN	PRODUCING ✓ <i>✓</i> Inj	DATE 10-29-13
-------------------------	---------	---	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	Ø		Ø		1930
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Accepted for Record Only

msb

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBD/MS
Title: ALCR	Re-test
E-mail Address: DNHC@chevron.com	
Date: 10-29-13	Phone: 575-631-9033
Witness:	

JAN 13 2014