

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

DEC 13 2013

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc	API Number 30-028-24363
---	-----------------------------------

Property Name (VGSAC) Vacuum Greysburg San Andres Unit	Well No. 45
--	-----------------------

1. Surface Location

UL - Lot C	Section 02	Township 18S	Range 34E	Feet from 1310	N/S Line FWL	Feet from 2530	E/W Line FWL	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN ☐	PRODUCING ☒	DATE 10-31-13
-------------------------	-------------------------------------	--	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	$\emptyset$	N/A	$\emptyset$	900	
Flow Characteristics					
Puff	Y/ ☒ N	Y/ ☒ N	Y/ ☒ N	Y/ ☒ N	
Steady Flow	Y/ ☒ N	Y/ ☒ N	Y/ ☒ N	Y/ ☒ N	
Surges	Y/ ☒ N	Y/ ☒ N	Y/ ☒ N	Y/ ☒ N	
Down to nothing	Y/ ☒ N	Y/ ☒ N	Y/ ☒ N	Y/ ☒ N	
Gas or Oil	Y/ ☒ N	Y/ ☒ N	Y/ ☒ N	Y/ ☒ N	
Water	Y/ ☒ N	Y/ ☒ N	Y/ ☒ N	Y/ ☒ N	


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Accepted for Record Only

MB

Signature: 	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: Area	Re-test
E-mail Address: sure@chevron.com	
Date: 10/31/13	Phone: 575-631-2223
Witness:	

JAN 13 2014