

DEC 13 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name

✓ Chevron USA Inc

API Number

30-025-25800

Property Name

✓ Central Vacuum Unit

Well No.

115

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
✓ 5	6	188	35E	1600	FSL	1500	FEL	LEA

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
✓ A		✓ Inj	10-29-2013

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	Ø	Ø	Ø		1290
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Accepted for Record Only

MSB

Signature: 	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBI/MS
Title: ALCR	Re-test
E-mail Address: DNLC@chevron.com	
Date: 10-29-13	Phone: 575-631-9033
Witness:	

JAN 13 2014