

DEC 13 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name <i>Chevron USA INC</i>				API Number <i>30-025-24317</i>					
Property Name <i>(V6SAU) Vacuum Gasburg San Andres Unit</i>				Well No. <i>18</i>					
Surface Location									
UT - Lot <i>k</i>	Section <i>01</i>	Township <i>18S</i>	Range <i>34E</i>	Feet from <i>1330</i>		N/S Line <i>FSL</i>	Feet from <i>1330</i>	E/W Line <i>FWL</i>	County <i>Lea</i>

Well Status

Well Status <i>A</i>	SHUT-IN	PRODUCING <i>Finj</i>	DATE <i>10-30-13</i>
-------------------------	---------	--------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	$\emptyset$	N/A	70 $\rightarrow$ 0	1000	
Flow Characteristics					
Puff	Y / N	Y / N	☒ Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / ☒ N	Y / N	
Surges	Y / N	Y / N	Y / ☒ N	Y / N	
Down to nothing	Y / N	Y / N	☒ Y / N	Y / N	
Gas or Oil	Y / N	Y / N	☒ Y / N	Y / N	
Water	Y / N	Y / N	Y / ☒ N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

C. bleed down in 10sec All gas.

Accepted for Record Only

MSB

Signature: <i>[Signature]</i>		OIL CONSERVATION DIVISION	
Printed name: <i>Danny Acosta</i>		Entered into RBDMS	
Title: <i>ALCR</i>		Re-test	
E-mail Address: <i>SNLC @ Chevron.com</i>			
Date: <i>10-30-13</i>	Phone: <i>575-671-9030</i>		
Witness:			

JAN 13 2014