

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOEBS OCD

DEC 13 2013

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc	REAPI Number 30-025-25711
Property Name Central Vacuum Unit	Well No. 100

7. Surface Location

UL - Lot F	Section 6	Township 18 S	Range 35 E	Feet from 1372	N/S Line F N L	Feet from 2544	E/W Line F W L	County LEA
----------------------	---------------------	-------------------------	----------------------	--------------------------	--------------------------	--------------------------	--------------------------	----------------------

Well Status

Well Status A	SHUT-IN	PRODUCING ✓ Inj	DATE 11/18/13
-------------------------	---------	---------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	0		0	250	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

> CO2 + water Injection Reported for 10 2013.
JAD. 11/13/14

FOR RECORD ONLY

Signature: 	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: ALCR	Re-test
E-mail Address: DNLC@chevron.com	
Date: 11/18/2013	Phone: 575-631-9033
Witness:	

JAN 13 2014