

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 13 2013

BRADENHEAD TEST REPORT

RECEIVED

Operator Name

✓ Chevron USA, Inc.

API Number

30-025-25733

Property Name

✓ Central Vacuum Unit

Well No.

93

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
M	31	17	35	10	S	1136	W	LEA

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
✓ A		✓ Dry	10-28-13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	Ø	Ø	Ø		1698
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

> CO2 Reported 10/2013. (2200 psi limit)
JAD 11/14/2014

FOR RECORD ONLY

JAD/OCD, 11/14/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBIMS
Title: ALCR	Re-test
E-mail Address: DNLC@chevron.com	
Date: 10-28-13	Phone: 575-631-9033
Witness:	

JAN 14 2014