

DEC 13 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name ✓ <i>Chevron USA INC.</i>						API Number <i>30-025-27967</i>			
Property Name ✓ <i>Central Vacuum Unit</i>						Well No. <i>157</i>			
7. Surface Location									
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet from	E/W Line	County
✓ <i>M</i>	<i>25</i>	<i>17N</i>	<i>34E</i>		<i>1150</i>	<i>FSL</i>	<i>75</i>	<i>FLC</i>	<i>LEA</i>
Well Status									
Well Status ✓ <i>A</i>		SHUT-IN <i>✓</i>		PRODUCING <i>✓</i> <i>Inj</i>		DATE <i>10-24-13</i>			

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	<i>Ø</i>	<i>Ø</i>	<i>Ø</i>		
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

✓ *Shut in due to Satellite upgrade.*

Accepted for Record Only
YMB

Signature: <i>Danny Acosta</i>		OIL CONSERVATION DIVISION	
Printed name: <i>Danny Acosta</i>		Entered into RBEMS	
Title: <i>ALCR</i>		Re-test	
E-mail Address: <i>DNLAC@chevron.com</i>			
Date: <i>10-24-13</i>	Phone: <i>575-631-9033</i>		
Witness:			

JAN 14 2014