

HOBBS OGD

DEC 13 2013

RECEIVED

Dist. 1
1625 N. French St., Hobbs, NM 88240
Phone: (505) 393-6161 Fax: (505) 393-6772

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CHEVRON USA, INC	API Number 30025 38002
Property Name (CVU) Central Vacuum Unit	Well No. 342

Surface Location

UL - Lot A	Section 36	Township 17S	Range 34S	East foot 82	N/S Line N	East foot 1186	SW 1/4 E	County Lea
----------------------	----------------------	------------------------	---------------------	------------------------	----------------------	--------------------------	--------------------	----------------------

Well Status

Well Status A	SITUATION Shut-in	PRODUCING X Inj	DATE 11/28/13
-------------------------	-----------------------------	---------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Intern	(B) Intern (I-Intern)	(C) Intern-Prod	(D) Prod-ET (Inter)	(E) ET (Inter)
Pressure	Ø	Ø	Ø	1556	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	Y / N
Steady Flow	Y / N	Y / N	Y / N	Y / N	Y / N
Surges	Y / N	Y / N	Y / N	Y / N	Y / N
Down to nothing	Y / N	Y / N	Y / N	Y / N	Y / N
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Y / N
Water	Y / N	Y / N	Y / N	Y / N	Y / N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

1002 Reported 10/2013;
(2200 psi limit) 11/4/2014.

FOR RECORD ONLY

SAB/ OGD 1/14/2014

Signature 		OIL CONSERVATION DIVISION	
Printed name Danny Asch		Entered into RBDMS	
Title Asch		Re-test	
E-mail Address danny@chevron.com			
Date 11/25/13	Phone 505-631-9033		
Witness			

JAN 14 2014