

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 13 2013

BRADENHEAD TEST REPORT

RECEIVED

API Number

Operator Name

✓ Chevron USA, Inc.

30-025-38637

Property Name

✓ Central Vacuum Unit

Well No.

455

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
✓ 8	36	172	34 E	1310	FN L	660	FW L	LEA

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
✓ A		✓ Int	10/28/13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	0	0	0	1700	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

> Water CO2 Reported 10/2013;
1500 / 2200 psi. S.A.D. 11/14/2014

FOR RECORD ONLY

SAD/OCD - 11/14/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: ALCR	Re-test
E-mail Address: DNLC@chevron.com	
Date: 10/28/13	Phone: 575-631-9033
Witness:	

JAN 14 2014