

Submit 1 Copy To Appropriate District
Office

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
20 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised July 18, 2013

HOBBS OCO

NOV 07 2013

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-22841 & 30-025-10436
1. Type of Well: Oil Well ☐ Gas Well ☒ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator CHEVRON USA INC.		6. State Oil & Gas Lease No.
3. Address of Operator 15 SMITH RD MIDLAND, TX 79705		7. Lease Name or Unit Agreement Name QUAIL QUEEN UNIT / OLLIE J BOYD
4. Well Location G 1980 feet from the NORTH line and 1980 feet from the EAST line Unit Letter F : 1980' feet from the NORTH line and 1980 feet from the WEST line Section 11 Township 19S Range 34E NMPM County LEA		8. Well Number 12 & 4
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3969' GR		9. OGRID Number 4323
		10. Pool name or Wildcat QUAIL QUEEN

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: 'BHTF Correction' ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

CHEVRON USA INC. HAS CORRECTED THE BRADENHEAD TESTS FOR THE QUAIL QUEEN UNIT #12 AND OLLIE J. BOYD #4 WELLS. SEE ATTACHED BRADENHEAD TESTS.

EMMANUEL JIMENEZ SPOKE WITH SYLVIA DICKEY ON 11/05/2013 TO CORRECT TEST INFORMATION.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Cindy Herrera-Murillo TITLE PERMITTING SPECIALIST DATE 11/05/2013

Type or print name CINDY HERRERA-MURILLO E-mail address: Cherreramurillo@chevron.com PHONE: 575-263-0431

For State Use Only

APPROVED BY: SAD/OCO **FOR RECORD ONLY** DATE 11/7/2013
Conditions of Approval (if any):

JAN 15 2014

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Chevron USA, INC.	API Number 30-025-22841
Property Name Quail Queen Unit	Well No. 12

Surface Location

UT - Lot G	Section 11	Township 19S	Range 34E	Feet from 1980	Feet from FNL	Feet from 1980	E/W Line FEL	County Lea
----------------------	----------------------	------------------------	---------------------	--------------------------	-------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status ST	Well Status Shut-In	Well Status Injecting	Well Status Producing	DATE 10-23-2013
--------------------------	-------------------------------	---------------------------------	---------------------------------	---------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm (1) Interm (2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	0			110	330
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	Y/N
Steady Flow	Y/N	Y/N	Y/N	Y/N	Y/N
Surges	Y/N	Y/N	Y/N	Y/N	Y/N
Down to nothing	Y/N	Y/N	Y/N	Y/N	Y/N
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Y/N
Water	Y/N	Y/N	Y/N	Y/N	Y/N

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

D. Production Casing -
- It took 15 seconds to blow down to 0 psi.

D. Column - Should be NO. ✓

SAS/OCO 11/7/2013.

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Justin Hobbs	Entered into RBDMS
Title: PSSS	Re-test
E-mail Address: JHobbs@chevron.com	
Date: 10/23/2013	Phone: 575-631-4228
Witness:	

