

HOBS OCD

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 13 2013

BRADENHEAD TEST REPORT

RECEIVED

Operator Name ✓ Chevron USA Inc	API Number 30-025-25811
Property Name Central Vacuum Unit	Well No. 14

7. Surface Location

UL - Lot E	Section 30	Township 17N	Range 35E	Feet from 2630	N/S Line FNL	Feet From 123F	E/W Line FEL	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status A	SHUT-IN	PRODUCING In	DATE 11/23/13
-------------------------	---------	------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	Ø		Ø	1600	
Flow Characteristics					
Pull	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

1 Per IPI 164 - (1578 psi limit) SADI
2 Violation Letter 1/20/14.
O.P.L.

FOR RECORD ONLY

Signature: Danny Acosta	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: ALCR	Re-test
E-mail Address: DNLC@chevron.com	
Date: 11/23/13	Phone: 575-631-9033
Witness:	

JAN 16 2014