

HOBBSOCD

DEC 13 2013

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name ✓ Chevron USA Inc.					API Number 30-025-38639				
Property Name ✓ Central Vacuum Unit					Well No. 457				
7. Surface Location									
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
✓ 5	36	17 S	34 E		1593	F N L	1912	F E L	LEA

Well Status

Well Status ✓ A	SHUT-IN	PRODUCING ✓ Inj	DATE 10/28/13
---------------------------	---------	---------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	0		0	1750	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

> Water Injection Reported 10/2013
> WFK-835 = 1500 psi
> O.P.L. Letter of Violation 1/2014.
SAD/ocd

FOR RECORD ONLY

SAD/ocd

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: ALCR	Re-test
E-mail Address: DNLC@chevron.com	
Date: 10/28/13	Phone: 575-631-9033
Witness:	

JAN 16 2014