

HOBBS OCD
DEC 13 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name ✓ Chevron USA Inc	API Number 30-025-02199
Property Name West Vacuum Unit	Well No. 20

7. Surface Location

UL - Lot 6	Section 34	Township 17N	Range 34E	Feet from 2310	N/S Line E N L	Feet from 1650	E/W Line F E L	County LEA
----------------------	----------------------	------------------------	---------------------	--------------------------	--------------------------	--------------------------	--------------------------	----------------------

Well Status

Well Status A	SHUT-IN SHUT-IN	PRODUCING ✓	DATE 11-7-13
-------------------------	---------------------------	-----------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Pre-4-Tubing	(E)Tubing
Pressure	Ø		Ø		Ø
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

> Shut In - No Reported Injection
as of 10/2013. 11/1/2014.

Accepted for Record Only

MMB 1/16/2014

Signature: Danny Acosta	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: ALCR	Re-test
E-mail Address: DNLC@chevron.com	
Date: 11-7-2013	Phone: 575-631-9033
Witness:	

JAN 16 2014