

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 13 2013

BRADENHEAD TEST REPORT

RECEIVED

Operator Name ✓ Chevron USA Inc	API Number 30-025-24112
Property Name ✓ North Vacuum Abo West Unit	Well No. 5

7. Surface Location

U/L - Lot D	Section 22	Township 17S	Range 34E	Feet from 660	N/S Line FNL	Feet from 660	E/W Line FWL	County LEA
-----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

Well Status TA	SHUT-IN ✓	PROBLEM Inj	DATE 11/11/13	TA
--------------------------	---------------------	-----------------------	-------------------------	-----------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	Ø		Ø		
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	


If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

Accepted for Record Only

MSB 1/16/2014

Signature: 	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: ALCR	Re-test
E-mail Address: DNLCA@chevron.com	
Date: 11/11/13	Phone: 575-631-9033
Witness:	

JAN 16 2014