

DEC 13 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name ✓ Chevron USA INC	API Number 30-025-25311
Property Name ✓ North Vacuum Abo West Unit	Well No. 7

7. Surface Location

UL - Lot ✓ F	Section 22	Township 17S	Range 34E	Feet from 2020	N/S Line FNL	Feet From 1980	E/W Line FWL	County LEA
------------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status ✓ Shut-in	SHUT-IN ✓	PRODUCING ✓	DATE 11/11/13
---------------------------------	---------------------	-----------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	Ø		100		Ø 3500
Flow Characteristics					
Puff	Y / N	Y / N	Y / Ø	Y / N	
Steady Flow	Y / N	Y / N	Ø / N	Y / N	
Surges	Y / N	Y / N	Y / Ø	Y / N	
Down to nothing	Y / N	Y / N	Ø / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / Ø	Y / N	
Water	Y / N	Y / N	Ø / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR ✓	FRESH	SALTY	SULFUR	BLACK
----------------	-------	-------	--------	-------

Remarks:

had 100# & blew down to 0 # (Clear Water)

> No Reported Injection as of
8/20/13. JAB 1/2014

Accepted for Record Only

MMB 1/16/2014

Signature: Danny Acosta	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBOMS
Title: ALCR	Re-test
E-mail Address: DNLC@chevron.com	
Date: 11/11/13	Phone: 575-631-9033
Witness:	

JAN 16 2014