

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 13 2013

RECEIVED

BRADENHEAD TEST REPORT

Operator Name ✓ <i>Chevron USA, Inc</i>	API Number <i>30-025-25726</i>
Property Name ✓ <i>Central Vacuum Unit</i>	Well No. <i>70</i>

7. Surface Location

UL - Lot ✓ <i>E</i>	Section <i>36</i>	Township <i>17N</i>	Range <i>34E</i>	Feet from <i>2630</i>	N/S Line <i>FNL</i>	Feet From <i>1310</i>	E/W Line <i>FWL</i>	County <i>LEA</i>
-------------------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status ✓ <i>AShutdown</i>	SHUT-IN ✓	PRODUCING <i>Inj</i>	DATE <i>10-24-13</i>
--	---------------------	-------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	<i>0</i>	<i>0</i>	<i>0</i>	<i>0</i>	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

*Failed MTTs
Shut In*

Accepted for Record Only
MRB

Signature: <i>Danny Acosta</i>	OIL CONSERVATION DIVISION
Printed name: <i>Danny Acosta</i>	Entered into RBE/MS
Title: <i>ALCR</i>	Re-test
E-mail Address: <i>DNHC@chevron.com</i>	
Date: <i>10-24-13</i>	Phone: <i>575-631-9033</i>
Witness:	

JAN 16 2014