

DEC 13 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

RECEIVED

✓	Operator Name Chevron USA, INC	API Number 30-025-25816
✓	Property Name Central Vacuum Unit	Well No. 28

7. Surface Location

UL - Lot P	Section 25	Township 17S	Range 34E		Feet from 1230	N/S Line FSL	Feet From 159	E/W Line FEL	County LEA
---------------	---------------	-----------------	--------------	--	-------------------	-----------------	------------------	-----------------	---------------

Well Status

Well Status C/A Shut IN	SHUT-IN	PRODUCING IN	DATE 10-25-13
----------------------------	---------	-----------------	------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed wuter, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure					
<u>Flow Characteristics</u>					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFOR	BLACK
-------	-------	-------	--------	-------

Remarks:

Well Failed MTR - Well Shattered.

Accepted for Record Only

msb

Signature: 		OIL CONSERVATION DIVISION
Printed name: Danny Acosta		Entered into RBDMS
Title: ALCR		Re-test
E-mail Address: DNLC@chevron.com		
Date: 10-25-13	Phone: 575-631-9033	
	Witness:	

JAN 16 2014