

DEC 13 2013

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6164 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Cherron USA, INC	* API Number 30-025-26001
Property Name Central Vacuum Unit	Well No. 141

2. Surface Location

UL - Lot M	Section 36	Township 17S	Range 34E	Feet from 10	N/S Line FSL	Feet from 1310	E/W Line FWL	County LEA
----------------------	----------------------	------------------------	---------------------	------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status SHUT-IN	PRODUCING IN	DATE 11-6-13
-------------------------------	------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	Ø	Ø	750 → 0		1681
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Ø N	Y / N	
Surges	Y / N	Y / N	Y / Ø	Y / N	
Down to nothing	Y / N	Y / N	Ø N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Ø N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR ✓	FRESH	SALTY	SULFUR	BLACK
----------------	-------	-------	--------	-------

Remarks:

750# blew down to 0#. (Clear water)
 > No Reported Injection 11/2013.
 > BHT Violation Due to Casing Pressure.
 > Letter 1/2014
 LAD/OCD 1/2014.

Accepted for Record Only

MJB

Signature: 	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBIMS
Title: ALCR	Re-test
E-mail Address: DNLC@chevron.com	
Date: 11-6-13	Phone: 575-631-9033
Witness:	

JAN 16 2014