

DEC 13 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name ✓ <u>Chevron USA, Inc.</u>	API Number <u>30-025-31786</u>
Property Name ✓ <u>Vacuum Gloria West Unit</u>	Well No. <u>30</u>

7. Surface Location

UL - Lot ✓ <u>5</u>	Section <u>25</u>	Township <u>17N</u>	Range <u>34E</u>	Feet from <u>2305</u>	N/S Line <u>FSL</u>	Feet from <u>1391</u>	E/W Line <u>FEL</u>	County <u>LEA</u>
-------------------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status ✓ <u>Shut-In</u>	<u>SHUT-IN</u>	PRODUCING ✓ <u>Inj</u>	DATE <u>11-5-13</u>
--	----------------	----------------------------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm (1-Interm (2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	<u>0</u>		<u>0</u>		<u>1320</u>
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

> No Inj Reported 11/2/13
> Per. 9714 1200 PSI.
> O.P.R. Letter of Violation
1/20/14

FOR RECORD ONLY

Signature: <u><i>Danny Acosta</i></u>	OIL CONSERVATION DIVISION
Printed name: <u>Danny Acosta</u>	Entered into RBDMS
Title: <u>A.L.C.R.</u>	Re-test
E-mail Address: <u>DNL.C@chevron.com</u>	
Date: <u>11-5-13</u>	Phone: <u>575-631-9033</u>
Witness:	

JAN 16 2014