

HOBBS OCD

JAN 16 2014

RECEIVED

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name chevron USA INC	*API Number 3002531874
Property Name V6WU	Well No. 106

7. Surface Location

BL - Lot 0	Section 36	Township 17	Range 24	Feet from 310	N/S Line S	Feet From 2630	E/W Line E	County LEA
----------------------	----------------------	-----------------------	--------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

Well Status SI	SHUT-IN ☒	PRODUCING ☐	DATE 12/01/13
--------------------------	--	---------------------------------------	-------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	0		150	0	
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

DID THIS BLEED DOWN?

Remarks:

well is producing but is not taking water because of facility issues.

> Violation letter - 1/2014
JAD 1/2014

Accepted for Record Only
MAB 1/16/2014

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Dane McEwen	Entered into RBDMS
Title: Prod Specialist	Re-test
E-mail Address: lnnb@chevron.com	
Date: 1/14/14	Phone: 575-942-3526
Witness:	

JAN 21 2014