

DEC 05 2013

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name	Property Name	API Number
✓ Chevron Midcontinent LP	✓ Lovington San Andres Unit	30-025-03812
Well No.		33

7. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
✓ A	1	17d	36E	660	FNL	660	FEL	LEA

Well Status

Well Status	SHUT-IN	PRODUCING	DATE
✓ A		✓ Iry	10/16/13

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A) Surf-Interm	(B) Interm(1)-Interm(2)	(C) Interm-Prod	(D) Prod-Tubing	(E) Tubing
Pressure	Ø	Ø	Ø		1700
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:


CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

✓ IPI - 3/1993 - 2193 psi ✓
81D 01/26/14

Accepted for Record Only

MYB

Signature: 	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBDMS
Title: ALC-R	Re-test
E-mail Address: DNLC@chevron.com	
Date: 10/16/2013	Phone: 575-631-9033
Witness:	

JAN 22 2014