

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

DEC 13 2013

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chervon N&T Inc	API Number 30-025-23905
Property Name North Vacuum Abo West Unit	Well No. 15

7. Surface Location

UL - Lot D	Section 27	Township 17S	Range 34E	Feet from 660	N/S Line FNL	Feet from 660	E/W Line FWL	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	------------------------	-------------------------	------------------------	----------------------

Well Status

Well Status TA	SHUT-IN ☒	PRODUCING ☐	DATE 11/11/13	TA
--------------------------	--	---------------------------------------	-------------------------	-----------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E)Tubing
Pressure	50		50		
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
--------------	--------------	--------------	---------------	--------------

Remarks:


had 50# of flow both blew down to 0#.
(clear water)

> Failed PT

> TA Status Expires 8/24/2016
SAD 1/2014

FOR RECORD ONLY

SAD/OCD.

Signature: 	OIL CONSERVATION DIVISION
Printed name: Danny Acosta	Entered into RBOMS
Title: ALCR	Re-test
E-mail Address: DNHC@chevron.com	
Date: 11/11/13	Phone: 575-631-9033
Witness:	

JAN 27 2014